



Orig Tree Position	Site	Original Tree Species	Confirm Reason For Removal	6 D's	Planting Notes	Original Tree Easting	Original Tree Northing	Replant Species	Replant Easting	Replant Northing
O/S 19 (immediately topside of driveway)	KENWOOD PARK ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in new 800mm pit outside 15 at lowerside of driveway (same as felled tree)	434402.81	385406.45	Corylus colurna	434402.8	385406.45
O/S 49	KENWOOD PARK ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in new 800mm pit o/s 49 centrally (same as felled tree)	434180.27	385497.04	Corylus colurna	434180.14	385496.83
O/S 47 ("Ashburnam")	KENWOOD PARK ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in new 800mm pit o/s 47 centrally (same as felled tree)	434187.98	385492.21	Corylus colurna	434188.74	385491.64
O/S 43 (topside outside 43)	KENWOOD PARK ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in new 800mm pit o/s 43 (same as felled tree)	434212.89	385479.84	Corylus colurna	434212.94	385480.21
O/S 41-43 (between the 2)	KENWOOD PARK ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in new 800mm pit o/s 41-43 between the two (same as felled tree)	434220.35	385476.79	Corylus colurna	434220.38	385476.78
O/S 41 (topside of 41 driveway)	KENWOOD PARK ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in new 800mm pit o/s 41 (topside of driveway) (same as felled tree)	434231.03	385471.19	Corylus colurna	434230.68	385471.05
O/S 23-25 (on corner of driveway)	KENWOOD PARK ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in new 800mm pit between 23-25 (same as felled tree)	434362.73	385418.23	Corylus colurna	434363.09	385417.9
O/S 37-39, bottomside driveway	KENWOOD PARK ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in new 800mm pit o/s 37-39 (same as felled tree)	434252.22	385462.04	Corylus colurna	434249.58	385463.32
O/S 33, OPPOSITE 26	KENWOOD PARK ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in new 800mm pit OPPOSITE 26 (same as felled tree)	434300.78	385442.89	Corylus colurna	434300.24	385443
O/S 31, (opposite 24)	KENWOOD PARK ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in new 800mm pit OPPOSITE 24 (same as felled tree)	434320.69	385435.09	Corylus colurna	434320.28	385434.98

Orig Tree Position	Site	Original Tree Species	Confirm Reason For Removal	6 D's	Planting Notes	Original Tree Easting	Original Tree Northing	Replant Species	Replant Easting	Replant Northing
O/S 45, centrally	KENWOOD PARK ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in new 800mm pit o/s 45 centrally (same as felled tree)	434198.32	385486.96	Corylus colurna	434198.27	385486.94
O/S 15, lowermost side of driveway	KENWOOD PARK ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in new 800mm pit outside 15 at lowerside of driveway (same as felled tree)	434461.04	385400.77	Corylus colurna	434461.39	385400.88
O/S 51	KENWOOD PARK ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in new 800mm pit o/s 51 in space between adjacent mature trees (same as felled tree)	434159.08	385508.57	Corylus colurna	434158.65	385508.68
O/S 13 (lowermost side o/s 13)	KENWOOD PARK ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in new 800mm pit outside 13 at lowermost end (same as felled tree)	434484.93	385401.7	Corylus colurna	434484.85	385401.75
O/S 28 "The Workshop", (bottomside driveway)	KENWOOD PARK ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in new 800mm pit o/s 28 (same as felled tree)	434293.63	385455.18	Corylus colurna	434293.16	385455.34